



Form Information

Form Name:	Compliance Follow Up Form
Submitter Name:	Cole Nichols (colen@horizonenvservices.com)
Submission Date:	May 10, 2019 1:11:43 PM MDT
Server Receive Date:	May 10, 2019 1:13:02 PM MDT
Reference Number:	20190510-18105937234
Location:	557 Airpark Dr, Durango, CO 81303, USA May 10, 2019 1:10:47 PM MDT [View Map]

Information

Name	colen@horizonenvservices.com
Date	May 9, 2019
Well Name	LINDNER GAS UNIT A 1
API Number	50670741900
Select State	Colorado
Work type	COGCC Inspection AR
Action Complete	Clean Up Weed Debris
Picture North to South	



Picture South to North



Picture East to West



Picture West to East



Additional photos



Completed work description

mowed and removed weed debris