



Form Information

Form Name: **Compliance Follow Up Form**
Submitter Name: Cole Nichols (colen@horizonenvservices.com)
Submission Date: Jun 5, 2019 8:43:05 AM MDT
Server Receive Date: Jun 5, 2019 8:44:31 AM MDT
Reference Number: 20190605-18108317237
Location: 557 Airpark Dr, Durango, CO 81303, USA
Jun 5, 2019 8:42:21 AM MDT [[View Map](#)]

Information

Name	colen@horizonenvservices.com
Date	Jun 4, 2019
Well Name	LINDNER GAS UNIT A 1
API Number	50670741900
Select State	Colorado
Work type	COGCC Inspection AR
Action Complete	Compliance Inspection Actions Other

Picture North to South



Picture South to North



Picture East to West



Picture West to East



Additional photos



Completed work description

marked rig anchors and selective weed spray