

Form Information

Form Name:	Compliance Follow Up Form
Submitter Name:	Cole Nichols (colen@horizonenvservices.com)
Submission Date:	May 31, 2019 3:41:05 PM MDT
Server Receive Date:	May 31, 2019 3:41:12 PM MDT
Reference Number:	20190531-18108011000
Location:	Unknown Location

Information

Name	colen@horizonenvservices.com
Date	May 31, 2019
Well Name	DULIN, ROBERT GAS UNIT 1
API Number	50670696200
Select State	Colorado
Work type	COGCC Inspection AR
Action Complete	Compliance Inspection Actions Other

Picture North to South



Picture South to North



Picture East to West



Picture West to East



Additional photos



Completed work description

Selectively treated Canada Thistle populations in the project area.