



Form Information

Form Name:	Compliance Follow Up Form
Submitter Name:	Clay Elkins (celkins@gobrainstorm.net)
Submission Date:	Jun 10, 2019 4:52:59 PM MDT
Server Receive Date:	Jun 10, 2019 9:10:27 PM MDT
Reference Number:	20190611-18108683917
Location:	Unknown Location

Information

Name	celkins@gobrainstorm.net
Date	Jun 10, 2019
Well Name	DULIN, ROBERT GAS UNIT 1
Select State	Colorado
Work type	COGCC Inspection AR
Action Complete	Compliance Inspection Actions Fencing Erosion Repairs Install Rock Run Down

Picture North to South



Picture South to North



Picture East to West



Picture West to East



Additional photos



Additional photos

