



Form Information

Form Name:	Compliance Follow Up Form
Submitter Name:	Cole Nichols (colen@horizonenvservices.com)
Submission Date:	Jun 7, 2019 4:52:22 PM MDT
Server Receive Date:	Jun 7, 2019 4:53:47 PM MDT
Reference Number:	20190607-18108545187
Location:	557 Airpark Dr, Durango, CO 81303, USA Jun 7, 2019 4:51:39 PM MDT [View Map]

Information

Name	colen@horizonenvservices.com
Date	Jun 6, 2019
Well Name	LOBATO GAS UNIT A 1
API Number	50670724800
Select State	Colorado
Work type	COGCC Inspection AR
Action Complete	Compliance Inspection Actions Clean Up Weed Debris

Picture North to South



Picture South to North



Picture East to West



Picture West to East



Additional photos



Additional photos



Additional photos



Completed work description

mowed no spray site