



Form Information

Form Name:	Compliance Follow Up Form
Submitter Name:	Reclamation Tablet (reclamationtablet)
Submission Date:	Dec 18, 2018 12:05:45 PM MST
Server Receive Date:	Dec 18, 2018 12:06:37 PM MST
Reference Number:	20181218-1894176846
Location:	321 Cowboy Trl, Durango, CO 81303, USA Dec 18, 2018 12:05:19 PM MST [View Map]

Information

Name	reclamationtablet
Date	Dec 18, 2018
Well Name	REA GAS UNIT 18U-03 2
API Number	50670870100
Select State	Colorado
Work type	COGCC Inspection AR
Action Complete	Clean Up Weed Debris
Picture North to South	



Picture South to North



Picture East to West



Picture West to East



Additional photos



Additional photos



Additional photos



Notes

additional photos are before pictures to show what we removed