



Form Information

Form Name:	Compliance Follow Up Form
Submitter Name:	Cole Nichols (colen@horizonenvservices.com)
Submission Date:	Jun 7, 2019 5:34:50 PM MDT
Server Receive Date:	Jun 7, 2019 5:36:15 PM MDT
Reference Number:	20190607-18108546117
Location:	557 Airpark Dr, Durango, CO 81303, USA Jun 7, 2019 5:33:55 PM MDT [View Map]

Information

Name	colen@horizonenvservices.com
Date	Jun 6, 2019
Location Name (Other)	ute 01a - 20 2
Location API (Other)	06706780
Select State	Colorado
Work type	COGCC Inspection AR
Action Complete	Compliance Inspection Actions Erosion Repairs Other

Picture North to South



Picture South to North



Picture East to West



Picture West to East



Completed work description

treated noxious weeds and fixed erosion channel