

Inspection Photos

API: 05-009-06135

Operator: SOVEREIGN OPERATING

Inspection Date: 6/13/2019



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 05-009-06135 | Date: 6/13/2019

Inspection Photos



Photo 1. Facing south toward the location. Crop has not reestablished.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-009-06135 | Date: 6/13/2019

Inspection Photos



Photo 2. Facing north toward the location. Crop has not reestablished.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-009-06135 | Date: 6/13/2019

Inspection Photos



Photo 3. Facing east at the surrounding crop.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-009-06135 | Date: 6/13/2019