



## Form Information

Form Name:	<b>Compliance Follow Up Form</b>
Submitter Name:	Clay Elkins (celkins@gobrainstorm.net)
Submission Date:	Jun 10, 2019 5:14:58 PM MDT
Server Receive Date:	Jun 10, 2019 9:10:43 PM MDT
Reference Number:	20190611-18108683919
Location:	Unknown Location

## Information

Name	celkins@gobrainstorm.net
Date	Jun 5, 2019
Well Name	KLUSMAN RANCHES GAS UNIT 2
Select State	Colorado
Work type	COGCC Inspection AR
Action Complete	Compliance Inspection Actions Erosion Repairs Install Rock Run Down Clean Up Contaminated Soils Repaired Berm Removed sediment from BMP's

Picture North to South



Picture South to North



Picture East to West



Picture West to East



Additional photos



Additional photos



Additional photos

