



Form Information

Form Name:	Compliance Follow Up Form
Submitter Name:	Clay Elkins (celkins@gobrainstorm.net)
Submission Date:	Jun 10, 2019 3:56:43 PM MDT
Server Receive Date:	Jun 10, 2019 9:42:33 PM MDT
Reference Number:	20190611-18108684871
Location:	Unknown Location

Information

Name	celkins@gobrainstorm.net
Date	Jun 3, 2019
Well Name	SO UTE 32- 8; 1- 7
Select State	Colorado
Work type	COGCC Inspection AR
Action Complete	Compliance Inspection Actions Erosion Repairs Install Rock Run Down Clean up Operator Debris Clean Up Contaminated Soils Grading of Well Pad

Picture North to South



Picture South to North



Picture East to West



Picture West to East



Additional photos



Additional photos



Additional photos

