

Pit Status Evaluation Form

Pit Overview:

Pit Name: Juhl 1	Facility ID: 118486
Current Status: Unknown	Status Date: 9/23/1999
Current Operator: Visual Optics Inc / 93390	
Updated Operator:	
Form 15 Pit Permit Doc #: 658313	Permit Date: 06/09/1978
Related Facilities: Juhl 1 05-123-08519; Location ID 406450	

County: Weld			
Township: 6N	Range: 61W	Section: 14	QQ: NENE
Original Latitude/ Longitude: 40.493796 / -104.168863			
Updated Latitude/ Longitude: /			
Basis for Location Change:			
Pit lat/lon not changed - no visible evidence of pit in aerial images			

Pit Inspection/Information Request:

Field Inspection Date:	Document #:
Pit Still Present in Field: No	
Visible Surface Impacts: <input type="checkbox"/> Stressed Vegetation <input type="checkbox"/> Surface Depression <input type="checkbox"/> Stained Soil <input type="checkbox"/> Other (see below)	
Inspection Notes:	
Operator Required to Submit Form: NA	Due Date:
Form Request Sent To:	Sent Date:

Pit Status Evaluation:

Pit Status Review Documents:

- | | | |
|--------------------------|---|------------------|
| <input type="checkbox"/> | Form 15 Pit Permit – Doc #: 658313 | Date: 06/09/1978 |
| <input type="checkbox"/> | Field Inspection(s) – Doc #: 200058 | Date: 08/05/1988 |
| | Doc #: 200052 | Date: 09/26/1997 |
| | Doc #: 873095 | Date: 9/15/1999 |
| <input type="checkbox"/> | Form 27 Remediation Workplan – Project #: | Date: |
| <input type="checkbox"/> | Form 4 Sundry Notice – Doc #: | Date: |
| <input type="checkbox"/> | COGIS Document – Doc #: | Date: |
| <input type="checkbox"/> | Pit Inventory – Doc #: | Date: |
| <input type="checkbox"/> | Duplicate Record – Duplicate Pit(s) #: | |
| <input type="checkbox"/> | Aerial Photo Verification (photos attached) | |
| <input type="checkbox"/> | Other: | |

Pit Status Determination

Updated Pit Status: Closed

Pit Status Date: 09/26/1997

Timing of Pit Closure:

Pit closed with PA of well in accordance with rules in effect at time of closure and site passed final reclamation inspection

Pit Status Review Summary: