

Inspection Photos

API#081-06415

Operator: Chandler & Associates

Inspection #: 692401105

Inspection Date: 6/14/19



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:

Overview of Location to Northeast. Insert is close up of gravel remaining on location & access road. Arrow indicates riser remaining on site.

June 14, 2019



Photo#2:
Riser remaining on Location.

June 14, 2019



Photo#3:
Close up of riser remaining on Location.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Chandler & Associates PA State API#081-06415



Photo#4:
View over Marker at center of location to Southwest.

June 14, 2019



Photo#5:
View of access road leading out of Location to Southwest.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Chandler & Associates PA State API#081-06415