

Inspection Photos
Location Name: Bower 10-53
Location ID: 302719



Photo 1: PREVIOUS photo of weeds at wellhead



Photo 2: CURRENT photo of weeds at wellhead