

Inspection Photos
Location Name: Weld 152 PAD
Location ID: 435175



Photo 1: Tank Battery (NO SIGN)



Photo 2: No labeling/placard



Inspection Photos
Location Name: Weld 152 PAD
Location ID: 435175



Photo 3: No labeling/placard



Photo 4: No labeling/placard



Inspection Photos
Location Name: Weld 152 PAD
Location ID: 435175



Photo 5: Stained soil in separator house



Photo 6: Stained soil in separator house



Inspection Photos
Location Name: Weld 152 PAD
Location ID: 435175



Photo 7: Stained soil in separator house



Photo 8: Stained soil in separator house



Inspection Photos
Location Name: Weld 152 PAD
Location ID: 435175



Photo 9: Stained soil in separator house



Photo 10: Stained soil in separator house