

K-20
API: 05-103-08554
Inspection: 679704532



Photo 1. Location.



K-20

API: 05-103-08554

Inspection: 679704532

Gas leaking



Photo 2. Gas leaks.