

Inspection Photos
Location Name: Elk Springs Unit 11D-18
API: 05-081-06805



Photo 1. Overview of location taken at entrance facing northeast.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Number: 689802800

Inspection Photos
Location Name: Elk Springs Unit 11D-18
API: 05-081-06805



Photo 2. Waste in broken container at wellhead.



Photo 3. Close-up of photo 2, broken container and contents.