

**County:** Adams

**Township:** 1S                      **Range:** 68W                      **Section:** 2                      **QQ:** SENE

**Original Latitude/ Longitude:** 39.984728 / -104.961714

**Updated Latitude/ Longitude:** 39.994941 / -104.963568

**Basis for Location Change:**

Location moved to former TB area (aerial imagery circa 1993). QQ and section corrected.

<b>Field Inspection Date:</b>	<b>Document #:</b>
<b>Pit Still Present in Field:</b> No	
<b>Visible Surface Impacts:</b> <input type="checkbox"/> Stressed Vegetation <input type="checkbox"/> Surface Depression <input type="checkbox"/> Stained Soil <input type="checkbox"/> Other (see below)	
<b>Inspection Notes:</b>	
<b>Operator Required to Submit Form:</b> NA	<b>Due Date:</b>
<b>Form Request Sent To:</b>	<b>Sent Date:</b>

## Pit Status Evaluation:

### Pit Status Review Documents:

- |                                     |   |                 |
|-------------------------------------|---|-----------------|
| <input type="checkbox"/>            | Form 15 Pit Permit – Doc #: NA                | Date: NA        |
| <input checked="" type="checkbox"/> | Field Inspection(s) – Doc #: 313642           | Date: 10/2/1996 |
|                                     | Doc #: 853281                                 | Date: 2/28/2000 |
|                                     | Doc #:  | Date:           |
| <input checked="" type="checkbox"/> | Form 27 Remediation Workplan – Project #: 283 | Date: 6/8/2000  |
| <input type="checkbox"/>            | Form 4 Sundry Notice – Doc #:                 | Date:           |
| <input type="checkbox"/>            | COGIS Document – Doc #:                       | Date:           |
| <input checked="" type="checkbox"/> | Pit Inventory – Doc #: 2314547                | Date: 2/11/1998 |
| <input checked="" type="checkbox"/> | Duplicate Record – Duplicate Pit(s) #: 102354 |                 |
| <input type="checkbox"/>            | Aerial Photo Verification (photos attached)   |                 |
| <input type="checkbox"/>            | Other:  |                 |

### Pit Status Determination

**Updated Pit Status: Closed**

**Pit Status Date: 1/1/2005**

#### Timing of Pit Closure:

Pit closure under remediation project #283, closed 1/1/2005

#### Pit Status Review Summary:

Duplicate of pit 102354. Records document an unlined earthen produced water pit on location. Pit was closed under remediation project #283, resolved 1/1/2005. Pit status has been changed to closed.