

Inspection Photos  
Location Name: Nessu-Kinder #16  
Location ID: 333124



**Photo 1 Unused equipment Samson post, horses head.**



**Photo 2 Well sign does not reflect correct operator or emergency contact number.**

**Inspection Photos**  
**Location Name: Nessu-Kinder #16**  
**Location ID: 333124**



**Photo 3 WH Unused equipment Misc. WH parts**

**Photo 4 Unused equipment (PU)**

**Inspection Photos**  
**Location Name: Nessu-Kinder #16**  
**Location ID: 333124**



**Photo 5 Unused equipment: Walking beam Misc. parts.**