

Inspection Photos

06/25/2019

Operator: MOUNTAIN PETROLEUM CORP -
60890

Location ID: 410610
Yuma County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC

Inspection Photos

Operator Name: MOUNTAIN PETROLEUM CORP - 60890

Location ID: 410610



Photo 1: Photo taken from southwest end of the well location, facing northeast. Photo shows reclamation area for the well location. Vegetation within the well area is predominantly undesirable weedy plant species such as Cheatgrass (*Bromus tectorum*) and Knotweed (*Polygonum arenastrum*)



Photo 2: Photo taken from the well location. Photo shows Knotweed (*Polygonum arenastrum*) on the location.

Inspection Photos

Operator Name: MOUNTAIN PETROLEUM CORP - 60890

Location ID: 410610



Photo 3: Photo taken from the well location. Photo shows Knotweed (*Polygonum arenastrum*) on the location.



Photo 4: Photo taken from north end of the well location, facing south. Photo shows reclamation area for the well location. Vegetation within the well area is predominantly undesirable weedy plant species such as Cheatgrass (*Bromus tectorum*) and Knotweed (*Polygonum arenastrum*)

Inspection Photos
Operator Name: MOUNTAIN PETROLEUM CORP - 60890
Location ID: 410610



Photo 5: Photo of the starting point for the **disturbance (well)** area transect, facing northeast.



Photo 6: Photo of the 50th point of the **disturbance (well)** area transect, facing northwest.

Inspection Photos

Operator Name: MOUNTAIN PETROLEUM CORP - 60890

Location ID: 410610



Photo 7: Photo of the 50th point of the **disturbance (well)** area transect, facing southeast.



Photo 8: Photo of the 50th point of the **disturbance (well)** area transect.

Inspection Photos
Operator Name: MOUNTAIN PETROLEUM CORP - 60890
Location ID: 410610



Photo 9: Photo of the end point for the **disturbance (well)** area transect, facing southwest.



Photo 10: Photo of the starting point for the **disturbance (facility)** area transect, facing northeast.

Inspection Photos

Operator Name: MOUNTAIN PETROLEUM CORP - 60890

Location ID: 410610



Photo 11: Photo of the 50th point of the **disturbance (well)** area transect, facing northwest.



Photo 12: Photo of the 50th point of the **disturbance (well)** area transect, facing southeast.

Inspection Photos

Operator Name: MOUNTAIN PETROLEUM CORP - 60890

Location ID: 410610



Photo 13: Photo of the 50th point of the **disturbance (well)** area transect.



Photo 14: Photo of the end point for the **disturbance (facility)** area transect, facing southwest.

Inspection Photos

Operator Name: MOUNTAIN PETROLEUM CORP - 60890

Location ID: 410610



Photo 15: Photo of the starting point for the **reference** area transect, facing east



Photo 16: Photo of the 50th point of the **reference** area transect, facing north.

Inspection Photos

Operator Name: MOUNTAIN PETROLEUM CORP - 60890

Location ID: 410610



Photo 17: Photo of the 50th point of the **reference** area transect, facing south.



Photo 18: Photo of the 50th point of the **reference** area transect.

Inspection Photos
Operator Name: MOUNTAIN PETROLEUM CORP - 60890
Location ID: 410610



Photo 19: Photo of the end point for the **reference** area transect, facing west