

## Pit Status Evaluation Form

### Pit Overview:

<b>Pit Name:</b> STATE OF COLORADO YB1-2-9	<b>Facility ID:</b> 102307
<b>Current Status:</b> Unknown	<b>Status Date:</b> 9/23/1999
<b>Current Operator:</b> BALDWIN PUMP & SUPPLY INC / 5925	
<b>Updated Operator:</b> H & R WELL SERVICES, INC - 36980	
<b>Form 15 Pit Permit Doc #:</b> NA	<b>Permit Date:</b> NA
<b>Related Facilities:</b> API # 001-06435 (Fac ID 201032), Location 375528; API # 001-07470 (Fac ID 202065); API # 001-07679 (Fac ID 202274); API # 001-07680 (Fac ID 202275)	

<b>County:</b> Adams			
<b>Township:</b> 1S	<b>Range:</b> 67W	<b>Section:</b> 16	<b>QQ:</b> NENE
<b>Original Latitude/ Longitude:</b> 39.968429 / -104.889102			
<b>Updated Latitude/ Longitude:</b> 39.969865 / -104.884813			
<b>Basis for Location Change:</b> Location updated based on aerial imagery (circa 1993).			

### Pit Inspection/Information Request:

<b>Field Inspection Date:</b>	<b>Document #:</b>
<b>Pit Still Present in Field:</b> No	
<b>Visible Surface Impacts:</b> <input type="checkbox"/> Stressed Vegetation <input type="checkbox"/> Surface Depression <input type="checkbox"/> Stained Soil <input type="checkbox"/> Other (see below)	
<b>Inspection Notes:</b>          	
<b>Operator Required to Submit Form:</b> NA	<b>Due Date:</b>
<b>Form Request Sent To:</b>	<b>Sent Date:</b>

## Pit Status Evaluation:

### Pit Status Review Documents:

- |                                     |   |                |
|-------------------------------------|---|----------------|
| <input type="checkbox"/>            | Form 15 Pit Permit – Doc #: NA                        | Date: NA       |
| <input checked="" type="checkbox"/> | Field Inspection(s) – Doc #: 698494                   | Date: 4/4/1985 |
|                                     | Doc #: 340193   | Date: 9/1/1998 |
|                                     | Doc #: 1075921  | Date: 1/8/2003 |
| <input type="checkbox"/>            | Form 27 Remediation Workplan – Project #:             | Date:          |
| <input type="checkbox"/>            | Form 4 Sundry Notice – Doc #:                         | Date:          |
| <input type="checkbox"/>            | COGIS Document – Doc #:                               | Date:          |
| <input checked="" type="checkbox"/> | Pit Inventory – Doc #: 2223845                        | Date: 1/2/1996 |
| <input checked="" type="checkbox"/> | Duplicate Record – Duplicate Pit(s) #: 114304, 114368 |                |
| <input checked="" type="checkbox"/> | Aerial Photo Verification (photos attached)           |                |
| <input type="checkbox"/>            | Other:  |                |

### Pit Status Determination

**Updated Pit Status: Closed**

**Pit Status Date:**

#### Timing of Pit Closure:

Associated wells PA 1992/2001; Location passed final inspection 1/8/2003.

#### Pit Status Review Summary:

Duplicate of pit 114304, 114368. Records document an unlined earthen produced water pit on location. Pit was backfilled prior to 9/1/1998 inspection. Wells were plugged and passed final reclamation inspection 1/8/2003; location is now a housing development/golf course. Pit status has been changed to closed.



