

## Pit Status Evaluation Form

### Pit Overview:

<b>Pit Name:</b> Babb 15-14	<b>Facility ID:</b> 110637
<b>Current Status:</b> Unknown	<b>Status Date:</b> 09/23/1997
<b>Current Operator:</b> Markus Production, Inc / 53790	
<b>Updated Operator:</b>	
<b>Form 15 Pit Permit Doc #:</b>	<b>Permit Date:</b>
<b>Related Facilities:</b> Babb 15-14 well API 05-123-15049; Location ID 327704	

<b>County:</b> Weld			
<b>Township:</b> 6N	<b>Range:</b> 61W	<b>Section:</b> 14	<b>QQ:</b> SWSE
<b>Original Latitude/ Longitude:</b> 40.482967 / -104.173128			
<b>Updated Latitude/ Longitude:</b> 40.481902 / -104.173719			
<b>Basis for Location Change:</b>			
Pit is visible in 2009, 2011, 2013, 2015 aerial images available in COGIS Maps			

### Pit Inspection/Information Request:

<b>Field Inspection Date:</b>	<b>Document #:</b>
<b>Pit Still Present in Field:</b> No	
<b>Visible Surface Impacts:</b> <input type="checkbox"/> Stressed Vegetation <input type="checkbox"/> Surface Depression <input type="checkbox"/> Stained Soil <input type="checkbox"/> Other (see below)	
<b>Inspection Notes:</b>	
<b>Operator Required to Submit Form:</b> NA	<b>Due Date:</b>
<b>Form Request Sent To:</b>	<b>Sent Date:</b>

## Pit Status Evaluation:

### Pit Status Review Documents:

- |                                     |   |                  |
|-------------------------------------|---|------------------|
| <input type="checkbox"/>            | Form 15 Pit Permit – Doc #:                 | Date:            |
| <input checked="" type="checkbox"/> | Field Inspection(s) – Doc #: 200098053      | Date: 10/17/2006 |
|                                     | Doc #:                                      | Date:            |
|                                     | Doc #:                                      | Date:            |
| <input type="checkbox"/>            | Form 27 Remediation Workplan – Project #:   | Date:            |
| <input checked="" type="checkbox"/> | Form 4 Sundry Notice – Doc #: 658308        | Date: 07/06/1998 |
| <input type="checkbox"/>            | COGIS Document – Doc #:                     | Date:            |
| <input type="checkbox"/>            | Pit Inventory – Doc #:                      | Date:            |
| <input type="checkbox"/>            | Duplicate Record – Duplicate Pit(s) #:      |                  |
| <input type="checkbox"/>            | Aerial Photo Verification (photos attached) |                  |
| <input type="checkbox"/>            | Other:                                      |                  |

### Pit Status Determination

**Updated Pit Status: Active**

**Pit Status Date: 07/06/1998**

#### Timing of Pit Closure:

Pit was closed after PA in well, sometime after 2010 no Form 27 received

#### Pit Status Review Summary:

Pit status changed to Active because pit closed without Form 27 while current rules are in effect.  
Operator notified .....