

**ELU A24-496 Pad**  
**Location # 458475**  
**Inspection # 689703240**



**H&P 329**



**Diesel tank missing volume.**  
**Diesel tank with out 110 % containment.**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**ELU A24-496 Pad**  
**Location # 458475**  
**Inspection # 689703240**



**Diesel tank missing volume.**  
**Diesel tank with out 110 % containment.**



**Diesel tank missing volume.**  
**Diesel tank with out 110 % containment.**

**ELU A24-496 Pad**  
**Location # 458475**  
**Inspection # 689703240**



**Diesel tank missing volume.**  
**Diesel tank with out 110 % containment.**



**Unlabeled 5 gallon bucket by diesel tank has no secondary containment..**



**ELU A24-496 Pad**  
**Location # 458475**  
**Inspection # 689703240**



**Unlabeled 5 gallon bucket by diesel tank has no secondary containment..**



**Unlabeled 5 gallon bucket by diesel tank has no secondary containment..**

**ELU A24-496 Pad**  
**Location # 458475**  
**Inspection # 689703240**



**Unlabeled tote in front of air compressor units have no secondary containment.**



**Unlabeled tote in front of air compressor units have no secondary containment.**