

Inspection Photos

API: 05-017-07428

Operator: P O & G OPERATING

Inspection Date: 6/21/2019



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 05-017-07428 | Date: 6/21/2019

Inspection Photos



Photo 1. Facing toward the tank battery east of the well.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-017-07428 | Date: 6/21/2019

Inspection Photos



Photo 2. There is oil stained soil and possible tank leakage.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-017-07428 | Date: 6/21/2019

Inspection Photos



Photo 3. There are oil staining around the tanks.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-017-07428 | Date: 6/21/2019

Inspection Photos



Photo 4. Berm around separator has holes and cat walk is tipped over.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-017-07428 | Date: 6/21/2019

Inspection Photos



Photo 5. This barrel near the pumpjack is tipped over and does not have any labels.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-017-07428 | Date: 6/21/2019

Inspection Photos



Photo 6. Unused equipment remains near pumpjack.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-017-07428 | Date: 6/21/2019

Inspection Photos



Photo 7. The well sign at the pumpjack is incorrect with operator name and emergency contact number.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-017-07428 | Date: 6/21/2019