

Inspection Photos

Location Name: FOSS - USX AA-66N63W /5SWSW

Location #: 306382



Photo #1

Foss - USX AA 5-25 (05-123-24562) Wellsite

Shut-In | SI

Weeds

from prior insp.



Photo #2

Foss - USX AA 5-25 Wellsite

Temporarily Abandoned | TA

Posted Emergency Number is NOT valid

Weeds remain at wellsite

Inspection Photos

Location Name: FOSS - USX AA-66N63W /5SWSW

Location #: 306382



Photo #3

Foss - USX AA 5-11, 5-25 Battery site

Shut-down

Stained soil under loadout

from prior insp.



Photo #4

Foss - USX AA 5-11, 5-25 Battery site

Abandoned

All equipment removed

Stained soil appears remediated