

Inspection Photos
Location Name: FOSS-USX AA-66N63W /5NESW
Location #: 310381



Photo #1
Foss-USX AA 5-11 (05-123-26327) Wellsite
Shut-In | SI
Weeds
from prior insp.



Photo #2
Foss-USX AA 5-11 Wellsite
Temporarily Abandoned | TA
Posted Emergency Number is NOT valid
Weeds appear mitigated

Inspection Photos

Location Name: FOSS-USX AA-66N63W /5NESW

Location #: 310381



Photo #3

Foss - USX AA 5-11, 5-25 Battery site

Abandoned

All equipment removed