

Inspection Photos

API: 05-017-07804

Operator: ANGUS NATURAL RESOURCES

Inspection Date: 6/21/2019



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-017-07804 | Date: 6/21/2019

Inspection Photos



Photo 1. Facing north toward the location. Location has been recontoured.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-017-07804 | Date: 6/21/2019

Inspection Photos



Photo 2. East side of the location facing northwest.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-017-07804 | Date: 6/21/2019

Inspection Photos



Photo 3. View of vegetation cover. There is predominately undesirable weeds (Kochia) growing throughout the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-017-07804 | Date: 6/21/2019

Inspection Photos



Photo 4. East side of the location facing west.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-017-07804 | Date: 6/21/2019

Inspection Photos



Photo 5. North side of the location facing south.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-017-07804 | Date: 6/21/2019

Inspection Photos



Photo 6. West side of the location facing east.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-017-07804 | Date: 6/21/2019

Inspection Photos



Photo 7. Facing west at the surrounding undisturbed CRP pasture.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-017-07804 | Date: 6/21/2019