

Inspection Photos
Location Name: CROW POINT 34-18 TR
API#: 05-071-06756
INSP. #: 695100966



PHOTO 1: WELLHEAD



PHOTO 2: WELL SIGN

Inspection Photos

Location Name: CROW POINT 34-18 TR

API#: 05-071-06756

INSP. #: 695100966



PHOTO 3: UNUSED EQUIPMENT ON LOCATION (UNUSED RISER). COMPLY WITH RULE 603.f. AND NTO REGARDING UNUSED RISERS. CA DATE 9/26/19.



PHOTO 4: UNUSED EQUIPMENT ON LOCATION. COMPLY WITH RULE 603.f. AND NTO REGARDING UNUSED RISERS. CA DATE 9/26/19.



Inspection Photos
Location Name: CROW POINT 34-18 TR
API#: 05-071-06756
INSP. #: 695100966




PHOTO 5: CHARD REDORD OF MIT