

Inspection Photos
Location Name: WARREN 23-7 TR
API#: 05-071-06749
INSP. #: 695100968



PHOTO 1: WELLHEAD



PHOTO 2: WELL SIGN

Inspection Photos
Location Name: WARREN 23-7 TR
API#: 05-071-06749
INSP. #: 695100968



PHOTO 3: UNUSED EQUIPMENT ON LOCATION (UNUSED RISER). COMPLY WITH RULE 603.f. AND NTO REGARDING UNUSED RISERS. CA DATE 9/26/19.



PHOTO 4: UNUSED EQUIPMENT ON LOCATION. COMPLY WITH RULE 603.f. AND NTO REGARDING UNUSED RISERS. CA DATE 9/26/19.

Inspection Photos
Location Name: WARREN 23-7 TR
API#: 05-071-06749
INSP. #: 695100968




PHOTO 5: MIT CHART RECORD

