

Inspection Photos

06/26/2019

Operator: MONAHAN* REX FAMILY TRUST -
59100

Location ID: 117501 (Pit)
Washington County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC

Inspection Photos

Operator Name: MONAHAN* REX FAMILY TRUST - 59100

Location ID: 117501 (Pit)



Photo 1: Photo taken from the west of the pit location, facing east. Photo shows no agricultural production (crop establishment) from the 2019 crop seeding is occurring within the pit.



Inspection Photos
Operator Name: MONAHAN* REX FAMILY TRUST - 59100
Location ID: 117501 (Pit)



Photo 2: Photo taken from the northwest corner of the pit, facing east. Photo shows no agricultural production from the 2019 crop seeding is occurring within the pit. Additionally, the pit walls remain evident with no growth.

Inspection Photos
Operator Name: MONAHAN* REX FAMILY TRUST - 59100
Location ID: 117501 (Pit)



Photo 3: Photo taken from the northwest corner of the pit, facing southeast. Photo shows no agricultural production from the 2019 crop seeding is occurring within the pit.



Inspection Photos
Operator Name: MONAHAN* REX FAMILY TRUST - 59100
Location ID: 117501 (Pit)



Photo 4: Photo taken from the northwest corner of the pit, facing south. Photo shows no agricultural production from the 2019 crop seeding is occurring within the pit.

Inspection Photos
Operator Name: MONAHAN* REX FAMILY TRUST - 59100
Location ID: 117501 (Pit)



Photo 5: Photo taken from the northeast corner of the pit, facing south. Photo shows no agricultural production from the 2019 crop seeding is occurring within the pit. Additionally, the pit walls remain evident with no growth.



Inspection Photos
Operator Name: MONAHAN* REX FAMILY TRUST - 59100
Location ID: 117501 (Pit)



Photo 6: Photo taken from the northeast corner of the pit, facing west. Photo shows no agricultural production from the 2019 crop seeding is occurring within the pit. Additionally, the pit walls remain evident with no growth.



Inspection Photos
Operator Name: MONAHAN* REX FAMILY TRUST - 59100
Location ID: 117501 (Pit)



Photo 7: Photo taken from the north end of the of the pit, facing south. Photo shows no agricultural production from the 2019 crop seeding is occurring within the pit.

Inspection Photos
Operator Name: MONAHAN* REX FAMILY TRUST - 59100
Location ID: 117501 (Pit)



Photo 8: Photo taken from the former access road, facing west. Photo shows crop appears to be sufficiently establishing on access road.

Inspection Photos
Operator Name: MONAHAN* REX FAMILY TRUST - 59100
Location ID: 117501 (Pit)



Photo 9: Photo taken from the adjacent reference area. Photo shows crop establishment on reference to compare to the disturbance area.

Inspection Photos
Operator Name: MONAHAN* REX FAMILY TRUST - 59100
Location ID: 117501 (Pit)



Photo 10: Photo taken from the adjacent reference area. Photo shows crop establishment on reference to compare to the disturbance area.