

Inspection Photos
Location Name: Lindblad PC MM 25-15
Location ID: 423085



Photo 1: Wellhead; CURRENT photo of unused equipment



Photo 2: PREVIOUS photo of unused equipment



Inspection Photos
Location Name: Lindblad PC MM 25-15
Location ID: 423085



Photo 3: Decommission Tag Visible



Photo 4: Tank Battery



Inspection Photos
Location Name: Lindblad PC MM 25-15
Location ID: 423085



Photo 5: PREVIOUS photo of unused equipment next to gas meter house




Photo 6: CURRENT photo of unused equipment next to gas meter house