

Inspection Photos
Location Name: Ishiguro 5
Location ID: 323348



Photo 1: Wellhead



Photo 2: Stained soil

Inspection Photos
Location Name: Ishiguro 5
Location ID: 323348



Photo 3: Tank Battery



Photo 4: Previous Operator

Inspection Photos
Location Name: Ishiguro 5
Location ID: 323348



Photo 5: Separator NOT anchored