

# Inspection Photos

API: 05-073-06311

Operator: NIGHTHAWK PRODUCTION

Inspection Date: 6/24/2019



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-073-06311 | Date: 6/24/2019

## Inspection Photos



**Photo 1.** Facing northeast toward the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-073-06311 | Date: 6/24/2019

## Inspection Photos



**Photo 2.** Facing east at the location. Vegetation is well established in the southern portion of the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-073-06311 | Date: 6/24/2019

## Inspection Photos



**Photo 3.** There is a bare area with no vegetation at the north center portion of the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-073-06311 | Date: 6/24/2019

## Inspection Photos



**Photo 4.** Northeast side facing southwest. There are undesirable weeds in this area.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-073-06311 | Date: 6/24/2019

## Inspection Photos



**Photo 5.** Northeast side facing south. There are undesirable weeds in this area.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-073-06311 | Date: 6/24/2019