

Laramie Energy LLC
API # 05-077-08667
Inspection # 696600201



Photo #1 Photo from Entrance of location



Photo #2 Photo from Entrance of location

Laramie Energy LLC
API # 05-077-08667
Inspection # 696600201



Photo # 3 Photo of Tank Battery



Photo # 4 Photo of Wellheads.

Laramie Energy LLC
API # 05-077-08667
Inspection # 696600201



Photo #5 Erosion is evident along un-stabilized slope at the NE side of location .



Photo #6 Erosion is evident along un-stabilized slope at the NE side of location .

Laramie Energy LLC
API # 05-077-08667
Inspection # 696600201



Photo #7 Storm Water Erosion moving off location on SE side of location along the access road



Photo #8 Storm Water Erosion moving off location on SE side of location along the access road