

**Inspection Photos**  
**Location Name: Richter USX AB 27-65HN**  
**Location ID: 420650**




**Photo 1 – Richter USX AB 27-05 Wellhead**



**Photo 2 – Richter USX AB 27-65HN**

**Inspection Photos**  
**Location Name: Richter USX AB 27-65HN**  
**Location ID: 420650**



**Photo 3 – Stained Soil at the bottom of the Hydraulic Power Unit**



**Photo 4 – Secondary containment at Hydraulic Power Unit has non-E & P waste**



**Inspection Photos**  
**Location Name: Richter USX AB 27-65HN**  
**Location ID: 420650**



**Photo 5 – Unused chemical drum**



**Photo 6 – Stained Soil at wellhead**