

Pit Status Evaluation Form

Pit Overview:

Pit Name: Gerturde L. King	Facility ID: 118373
Current Status: Unknown	Status Date: 09/23/1999
Current Operator: Chevron USA Inc / 16700	
Updated Operator:	
Form 15 Pit Permit Doc #: 383580	Permit Date: 04/21/1983
Related Facilities: Location ID 405185 Well API 05-123-05524	

County: Weld			
Township: 8N	Range: 66W	Section: 22	QQ: SESW
Original Latitude/ Longitude: 40.641911 / -104.765834			
Updated Latitude/ Longitude: /			
Basis for Location Change:			
No evidence for actual location of pit			

Pit Inspection/Information Request:

Field Inspection Date:	Document #:
Pit Still Present in Field: No	
Visible Surface Impacts: <input type="checkbox"/> Stressed Vegetation <input type="checkbox"/> Surface Depression <input type="checkbox"/> Stained Soil <input type="checkbox"/> Other (see below)	
Inspection Notes:	
Operator Required to Submit Form: NA	Due Date:
Form Request Sent To:	Sent Date:

Pit Status Evaluation:

Pit Status Review Documents:

- | | | |
|--------------------------|---|------------------|
| <input type="checkbox"/> | Form 15 Pit Permit – Doc #: 383580 | Date: 04/21/1983 |
| <input type="checkbox"/> | Field Inspection(s) – Doc #: | Date: |
| | Doc #: | Date: |
| | Doc #: | Date: |
| <input type="checkbox"/> | Form 27 Remediation Workplan – Project #: | Date: |
| <input type="checkbox"/> | Form 4 Sundry Notice – Doc #: | Date: |
| <input type="checkbox"/> | COGIS Document – Doc #: | Date: |
| <input type="checkbox"/> | Pit Inventory – Doc #: | Date: |
| <input type="checkbox"/> | Duplicate Record – Duplicate Pit(s) #: | |
| <input type="checkbox"/> | Aerial Photo Verification (photos attached) | |
| <input type="checkbox"/> | Other: | |

Pit Status Determination

Updated Pit Status: Closed

Pit Status Date:

Timing of Pit Closure:

pre 1997

Pit Status Review Summary:

Pit permit states that "This pit was built to serve as a bleed off pit for the King water injection station." There is no evidence in field inspections or aerial imagery of a pit at the King injection well. Pits at the Pierce central battery formerly operated by Chevron and Stelbar were closed - ref Remediation #9091