



99999999

ADO OIL & GAS CONSERVATION COMMISSION  
FIELD INSPECTION FORM

C

<input type="checkbox"/> NOTICE OF UNSATISFACTORY INSPECTION		1120 Lincoln Street, Suite 801 Denver, CO 80203 (303)894-2100	
<input type="checkbox"/> NOTICE OF SATISFACTORY INSPECTION			
API No. 05- 069 - 5141		LEASE NAME: DOUGLAS STATE R-1	
LOCATION: SW NW 36 9N 69W		OPERATOR: WALSH	
DATE: 5/2/95		INSPECTOR: SHELTON	
Insp. Type: CA	Insp. Status: PA	PA: Y (N)	Pass/Fail: P (F) Viol.: Y (N) NOV: Y N

INSPECTION ITEM	COMMENTS	INPUT
Well ID Signs		
Pits (Reserve/Production)		
Fences		
Tank Battery Equipment		
Fire Walls/Berms/Dikes		
General Housekeeping		
Spills (Oil/Water)		
Bradenhead		
Drilling Well/Workover		
Surface Rehabilitation	CIBP SET / WESTERN SERVICE WORKING PRODUCTION PIPE FOR PULLING	/
Miscellaneous	TB SITE RESTORED	/

CORRECTIVE ACTION REQUIRED:



00259982

Date Corrective Action Required By:

Date Remedied:

This report is a Notice of Inspection. The Commission requires that you correct any deficiencies shown on this report in a timely manner. Failure to comply may result in enforcement action by the Commission.