

Laramie Energy LLC
API # 05-077-08701
Inspection # 696600222



Photo # 1 Photo at entrance of location
No Battery sign



Photo #2 Photo of location

Laramie Energy LLC
API # 05-077-08701
Inspection # 696600222



Photo #3 Photo of tank battery
Containment berm in need of maintenance
No Battery sign

Photo #4 Photo of Pump Jack and well head sign

Laramie Energy LLC
API # 05-077-08701
Inspection # 696600222



Photo #5 Containment Berm in need of maintenance



Photo #6 Trash and Debris on location

Laramie Energy LLC
API # 05-077-08701
Inspection # 696600222



Photo #7 Containment Berm erosion, Berm in need of maintenance



Photo #8 Erosion is evident along un-stabilized slope on south and SE side of location . No BMP's in place

Laramie Energy LLC
API # 05-077-08701
Inspection # 696600222



Photo # 9 Erosion is evident along un-stabilized slope on East side of location . No BMP's in place



Photo #10 Erosion is evident along un-stabilized slope on North side of location . No BMP's in place