

# *Inspection Photos*

*Location #312708*

*Operator: Fram*

*Inspection #: 692401126*

*Inspection Date: 6/21/19*



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Photo#1:  
Overview of Location to South.

June 21, 2019



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Fram Jensen Loc#312708





**Photo#2:**  
Tall stands of Kochia are growing on Location.

June 21, 2019



**Photo#3:**  
Tall stands of Kochia are growing on Location and weeds are growing around equipment.

Inspection Photos: Fram Jensen Loc#312708





**Photo#4:**  
Access Road is not maintained.

June 21, 2019



**Photo#5:**  
Access Road is not maintained.