

Inspection Photos

Location #334472

Operator: Fram

Inspection #: 692401130

Inspection Date: 6/21/19



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Overview of Location to West.

June 21, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Fram Jensen Loc#334472



Photo#2:

Location has desiccated (dead), and new growth, ruderal/debris weeds on Pad & Interim areas.



Photo#3:

Location has desiccated (dead), and new growth, ruderal/debris weeds on Pad & Interim areas.

June 21, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Fram Jensen Loc#334472



Photo#4:
There are Stormwater Concerns at Northwest
portion of site.

June 21, 2019



Photo#5:
There are Stormwater Concerns at Southeast
portion of site



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Fram Jensen Loc#334472