

Laramie Energy LLC  
API # 05-077-10010  
Inspection # 696600183



Photo #1 Photo from Entrance of location



Photo #2 Photo from Entrance of location

Laramie Energy LLC  
API # 05-077-10010  
Inspection # 696600183



Photo # 3 Photo of tank Battery



Photo # 4 Photo of Wellheads.



Laramie Energy LLC  
API # 05-077-10010  
Inspection # 696600183



**Photo # 5 Photo of Drill Cuttings on location not contained.  
Needs BMP**



**Photo # 6 Photo of Drill Cuttings on location not contained.  
Needs BMP**



Laramie Energy LLC  
API # 05-077-10010  
Inspection # 696600183



**Photo # 7 Photo Photo of Drill Cuttings on location not contained. Needs BMP**



**Photo # 8 Photo of Sediment Trap feeding retention pond needs maintenance.**



Laramie Energy LLC  
API # 05-077-10010  
Inspection # 696600183



**Photo # 9 Photo of Sediment Trap feeding retention pond needs maintenance.**



**Photo #10 Photo of un-stabilized slope on West side of location**



Laramie Energy LLC  
API # 05-077-10010  
Inspection # 696600183



**Photo # 11 Photo of un-stabilized slope on West side of location**



**Photo #11 Photo of sediment trap, BMP maintenance on North side of location**



Laramie Energy LLC  
API # 05-077-10010  
Inspection # 696600183



**Photo # 12 Sediment trap needs maintenance.**



**Photo # 13 Gravel over North side Berm**



Laramie Energy LLC  
API # 05-077-10010  
Inspection # 696600183



Photo #14 Gravel over North side Berm



Photo #15 Gravel over North side Berm