

Inspection Photos

API: 05-061-06847

Operator: MULL DRILLING COMPANY

Inspection Date: 6/5/2019



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 05-061-06847 | Date: 6/5/2019

Inspection Photos



Photo 1. Facing northwest along the access road toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-061-06847 | Date: 6/5/2019

Inspection Photos



Photo 2. Facing north from the access road. A cattle tank is located at the southeast corner of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-061-06847 | Date: 6/5/2019

Inspection Photos



Photo 3. Facing west at the edge of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-061-06847 | Date: 6/5/2019

Inspection Photos



Photo 4. Facing southwest toward the location. Cattle feeders are placed in this area. The water well is located at the southern edge of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-061-06847 | Date: 6/5/2019

Inspection Photos



Photo 5. Facing south toward the water well at Lat/Long:38.44507,-102.47552.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-061-06847 | Date: 6/5/2019

Inspection Photos



Photo 6. Facing northwest toward the corals standing near water well.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-061-06847 | Date: 6/5/2019

Inspection Photos



Photo 7. Facing southwest toward the corals.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-061-06847 | Date: 6/5/2019

Inspection Photos



Photo 8. Facing southwest toward the cut slope of the location which has been resloped but is full of weeds.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-061-06847 | Date: 6/5/2019

Inspection Photos



Photo 9. View of weed growth throughout the location. Kochia; Pennycress; Ragweed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-061-06847 | Date: 6/5/2019

Inspection Photos



Photo 10. Standing at the north side of the location facing southwest toward the corals.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-061-06847 | Date: 6/5/2019

Inspection Photos



Photo 11. Standing at the north side of the location facing southeast toward water well at the right of photo and water tank at left of the photo.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-061-06847 | Date: 6/5/2019

Inspection Photos



Photo 12. Standing at the north side of the location facing north toward the surrounding undisturbed pasture. Vegetation consist of Six week fescue, Sand sage, Sand dropseed, Blue grama, among other species.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-061-06847 | Date: 6/5/2019