

WELL SITE INSPECTION FORM



00271811

WELL NAME Champlin Res. #1
OPERATOR Walsh
LOCATION SWSW 25-9N-G9W
FIELD Douglas Lake

API NUMBER 05 - -
PERMIT NUMBER _____
COUNTY Larimer
INSPECTOR SP

AL/PA/DA INSPECTION RESULTS:

PASS(Y) _____ FAIL(N) _____ DATE _____

WELL STATUS:

FN _____ FD _____ WO _____

=====

DATE OF INSPECTION BEFORE/DURING DRILLING _____

CASING SIZE _____ DEPTH SET _____ CMT VOL _____ WOC _____
CONSISTENT WITH APD CASING PROGRAM? _____ RETURNS _____
RIG _____ BOP'S _____ CONTACT _____

DATE OF INSPECTION BEFORE/DURING/AFTER COMPLETION _____

PIPE SET? _____ COMPLETION RIG/ACTIVITY _____
DRILLING PITS: CLOSED _____ OPEN _____ WELLHEAD SYSTEM INSTALLED _____
TANK ID: YES _____ NO _____ NA _____ WELL SIGN: YES _____ NO _____
SKIM PIT: _____ gal TANKS: () _____ bbls
EQUIPMENT _____

BRADENHEAD PRESSURE _____ FLUID: NO _____ YES _____ TYPE _____
METER RUN: YES _____ NO _____ WELL STATUS: PR _____ TA _____ SI _____ WELL CAT 3- _____

AL/PA/DA INSPECTION

DATE PLUGGED: _____ DATE PERMIT EXPIRED: _____
HOLE PLUGGED: YES _____ NO _____ PITS BACKFILLED: YES _____ NO _____
MATERIAL BURIED: YES _____ NO _____ NA _____ SITE CLEAN: YES _____ NO _____
BOND RELEASE OK: YES _____ NO _____ FED _____ HOLE MARKER: YES _____ NO _____

DATE OF SAFETY/STATUS INSPECTION 6/17/88

COMMENTS Well T.A., 4 1/2" welded to valve
No surf. equip., all pits leveled

