

**Inspection Photos**  
**Location Name: Nielson #3**  
**API: 05-007-06116**



**Nielson #3 pump jack and well head.**



**Nielson #3 tank battery.**

**Inspection Photos**  
**Location Name: Nielson #3**  
**API: 05-007-06116**



**Stained soil beneath load out valve.**



**AST is stained with oil.**