

Inspection Photos
Location Name: Nielson #4
API: 05-007-06117



Nielson #4 pump jack and well head.



Nielson #4 tank battery. Secondary containment berm shared with Albert Martinez #1 ASTs.

Inspection Photos
Location Name: Nielson #4
API: 05-007-06117



Absorbent granules observed around the well head during this inspection.



Nielson #4 300 bbl. AST. Tamper evident seal on load out valve handle.