

Reclamation Inspection

June 25, 2019

Operator: K P KAUFFMAN COMPANY INC - 46290

Location ID: 455229

Inspection Document #: 697500263

Weld County, CO

NWSW Section 20 T2N R66W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: SPILL/RELEASE POINT
Location ID: 455229



Google Earth aerial imagery from May 31, 2018. Image illustrates disturbance related to a spill/release point. Red line = ~5300 square feet of an excavated area that was mapped back in August 2018. Two photos were taken on June 25, 2019 at the approximate western and eastern extents of the observed stunted crop growth.

Inspection Photos
Location Name: SPILL/RELEASE POINT
Location ID: 455229



Photo 1. Photo taken from the approximate eastern extent of the stunted crop growth, facing West. This area is within the excavated spill/release area.

Inspection Photos
Location Name: SPILL/RELEASE POINT
Location ID: 455229



Photo 2. Photo taken from the approximate western extent of the stunted crop growth, facing East. This area is within the excavated spill/release area.