

Inspection Photos

API: 05-071-07437

Operator: TIMBER CREEK OPERATING LLC

Inspection Date: 7/1/2019



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-07437 | Date: 7/1/2019

Inspection Photos



Photo 1. The culvert was cleaned out along the road. Material put on the road contains large rocks.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-07437 | Date: 7/1/2019

Inspection Photos



Photo 2. Stormwater flowing across the road shown in the previous photo has not been repaired.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-07437 | Date: 7/1/2019

Inspection Photos



Photo 3. Facing toward the well site. There is no secondary containment around produced water tank.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-07437 | Date: 7/1/2019

Inspection Photos



Photo 4. The sign has been installed but has incorrect operator name.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-07437 | Date: 7/1/2019

Inspection Photos



Photo 5. The oily waste has not been cleaned up since previous inspection.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-07437 | Date: 7/1/2019