

Inspection Photos
Location Name: Surprise Unit 2-08H
Location ID: 436801



Photo 1. Overview of location taken standing on topsoil pile looking west. Cuttings in left center of photo.



Photo 2. Cuttings.



Inspection Photos
Location Name: Surprise Unit 2-08H
Location ID: 436801



Photo 3. Cuttings.



Photo 4. Wattles becoming debris.

