

Inspection Photos
Location Name: Susan/Western Battery
Location ID: 323754



Photo 1: Centralized Tank Battery



Photo 2: No BBLs or contents labeled