

# Inspection Photos

API: 05-071-07416

Operator: TIMBER CREEK OPERATING LLC

Inspection Date: 7/1/2019



**COLORADO**

Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-071-07416 | Date: 7/1/2019

## Inspection Photos



**Photo 1.** Vehicle ruts remain along the road which is a conveyance for stormwater erosion.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-071-07416 | Date: 7/1/2019



## Inspection Photos



**Photo 2.** Vehicle ruts remain along the road which is a conveyance for stormwater erosion.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-071-07416 | Date: 7/1/2019



## Inspection Photos



**Photo 3.** There is erosion occurring along the side of the road. No BMP's present.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-071-07416 | Date: 7/1/2019

## Inspection Photos



**Photo 4.** Facing toward the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-071-07416 | Date: 7/1/2019