

Caerus Piceance LLC
API # 05-077-08679
Inspection # 696600246



Photo #1 Photo of Tank Battery sign at entrance attached to meter run



Photo #2 photo from entrance of location

Caerus Piceance LLC
API # 05-077-08679
Inspection # 696600246



Photo #3 photo of tank battery



Photo #4 photo of Wellhead

Caerus Piceance LLC
API # 05-077-08679
Inspection # 696600246



Photo #5 Trash or unused equipment on location



Photo #6 Trash or unused equipment on location.